



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

September 6, 2007

Supervisor 1027

Mine Name: Volite
Operator Name: Park Geological Consultants

Permit number: M/041/036
Inspection Date: August 28, 2007
Time: 8:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none.
Mine Status: Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:

On June 22, 2007, the Division notified Mr. Park that his proposed NOI was complete and that he needed to provide the reclamation surety and contract within 30 days. To date, the surety has not been provided. The Division sent a second request for surety on September 17, 2007.

Permit fees have not been paid for this year.

During this inspection, the area indicated on the map (NOI) was searched. Mining at this site has not commenced.

Conclusions and Recommendations:

If surety and permit fees are not received within the 30- day time frame given, then the Division should consider withdrawing its conditional acceptance and close this file.

Inspector's Signature _____

LK:pb

O:\M041-Sevier\S0410036 Volite\inspections\insp-08282007.doc